


Meter Base Adapters with Test Switches for Meter Verification Testing

Have meters you want to test, but don't have test switches. No problem. Spinlab now offers meter bases adapters equipped with test switches to allow you to easily check the accuracy of your meter and meter circuit.

Meter Bases Adapters with Test Switches Allow You to Test Any CT Rated Meter

If you don't have test switches, all you need is a Type S meter base adapter, and you can perform a meter verification test on any CT rated meter. Simply remove the meter, plug in the meter base adapter with a test switch, plug the meter into the meter base adapter, and you are ready to verify the accuracy of your meter. Different meter types require different meter base adapters with test switches:

- For connection to ringless and ring type (-R) meter bases
- One meter base adapter tests Form 3 & 4 meters (600-MV-MB1)
- One meter base adapter tests Form 5 meters (600-MV-MB2)
- One meter base adapter tests Form 6, 8, & 9 meters (600-MV-MB3)
- 3 adjustable slides hold the meter base adapter in place
- Plastic cover over the test switches to protect the operator
- Shorting bar for all current connections
- Open circuit switch for all voltage connections



Spinlab Utility Instrumentation

3110 Henson Road
Suite A-1
Knoxville, TN
37921

Office: (865) 212-9881
Fax: (865) 212-9886
E-Mail: sales@spinlabinc.com
Web Address: spinlabinc.com